

Exide Photographs
8-12-14



Upper Containment Building. Reddish colored materials if filter cake. The other stockpiles are lead-bearing materials destined to be placed in rotary kiln or blast furnace.



Inoperable containment building leak detection monitoring system.



Potholes in containment building. Note: The other surface areas are pot marked.



Lower containment building. Sludge materials to be reclaimed for lead. On the other side of the sump reportedly was the location for the second leak detection monitoring system. However, Exide if that was the location of the panel.



No panel. Red circle may have been electrical conduit for leak detection monitoring system.